

## TELEVISION TECHNICAL BULLETIN

---

**MODELS**     37GQ20H

**SYMPTOM**    Dead; power supply not running

**ACTION**       Replace R701 and R702 resistors with the part number listed below.

<b><u>REF NO</u></b>	<b><u>DESCRIPTION</u></b>	<b><u>PART NUMBER</u></b>	<b><u>PRICE CODE</u></b>
R701	Resistor	VRC-MA2HG474J*	AA
R702	Resistor	VRC-MA2HG474J*	AA

---

**Sharp Electronics (UK) Limited**

Reference PQA116

Revision 1

White – Carry out as required  
Yellow – Carry out as required and whenever the unit comes in for service  
Red – Carry out on all units

