

TELEVISION TECHNICAL BULLETIN

MODELS 37GQ20H 37GQ20IR

REASON Correction of IC1001 part number.

ACTION Update your service manual

<u>REF NO</u>	<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>PRICE CODE</u>
IC1001	IC with software for H (UK) models	CH-IX1796CJH4	AM
IC1001	IC with software for IR (EIRE) models	CH-IX1796CJS5	AM

Sharp Electronics (UK) Limited

Reference SP004800X
Revision 1

White – Carry out as required
Yellow – Carry out as required and whenever the unit comes in for service
Red – Carry out on all units

